

SN36 re-calibrated

Submitted by MattWingo on Tue, 2013-05-07 21:26

Date:

Tuesday, May 7, 2013 - 21:00

Instrument List:

- [Yellow](#)

Discussion:

SN37 and SN36 were visited today.

SN37 calibration checked and looked good.

SN36 calibration checked and looked terrible. A plane test was performed which resulted in good diameter and oblateness. However, plane distances are now low (4.5 mm at the lowest).

SN35 and SN25 will be visited tomorrow.
